

Reference	SSM71916
Models	Range Rover Evoque / L538
Title	Unexplained loss of coolant
Category	Engine
Last modified	21-Jul-2014 00:00:00
Symptom	402000 Cooling System Concerns

ContentIssue:

The factory would like to gain a deeper understanding of the issues surrounding 'continual unexplained low coolant level' on 2.0GTDI L538 (Evoque) vehicles.

Action:

In all cases whereby a technician identifies the symptoms detailed in LTB00502V2 (re-seal of core plugs) but the vehicle is not within the vin range (H- -H-), Please raise a TA before any repair work is carried out and the technical assistant will advise you accordingly.