



Service Bulletin

File in Section: -

Bulletin No.: PIC5677A

Date: April, 2014

PRELIMINARY INFORMATION

Subject: Timeshift Function Inoperative

Models: 2010-2011 Buick Lacrosse
2011 Buick Regal
2010-2011 Cadillac SRX
2010-2011 Chevrolet Equinox
2011 Chevrolet Cruze
2010-2011 GMC Terrain
Equipped with RPO UYS Navigation Radio

This PI was superseded to update recommendations. Please discard PIC5677.

Condition/Concern

Some customers may complain that the timeshift feature is inoperative (Timeshift is the ability to pause live radio).

Recommendation/Instructions

If this concern is encountered, replace the radio with the latest part number listed in the parts catalog and reevaluate for concern.

Important: Equivalent refurbished radios may be received with a different part number.

Warranty Information

For vehicles repaired under warranty use:

| Labor Operation | Description | Labor Time |
|-----------------|-------------------|------------------------------------|
| 3420840 | Radio Replacement | Use Published Labor Operation Time |