

| | |
|----------------------|--|
| Reference | SSM72302 |
| Models | F-TYPE / X152 XE / X760 XJ / X351 |
| Title | B1412-96 is being flagged in the Gateway Module |
| Category | Electrical |
| Last modified | 11-Jun-2015 00:00:00 |
| Symptom | 203000 Basic Electrical |
| Content | <p>Note: This is only applicable to the following vehicles and models years XJ(X351) 13MY onwards F Type(X152) 14MY onwards XE(X760) 16MY onwards.</p> <p><u>Issue</u> B1412-96 being flagged in the Gateway Module</p> <p><u>Cause</u> Under Investigation.</p> <p><u>Action</u> False log of DTC 1412-96 in the Gateway Module and will not clear due to internal software issues. This will not affect the vehicle performance and is not visible to the customer.</p> <p>If DTC 1412-96 is identified:</p> <ol style="list-style-type: none">1. Do not replaced the Gateway Module for this DTC.2. Do not replace the Quiescent Relay Box for this DTC. <p>SDD will be updated in due course.</p> |