
Reference	SSM72836
Models	F-PACE / X761
Title	`Creak Noise` From Rear Suspension
Category	Chassis
Last modified	23-Jun-2016 00:00:00
Symptom	304000 Suspension System

Content

Issue: A 'creak noise' may be evident from the rear of the vehicle while driving.

Cause: This may be caused by deflection of the rear coil spring top mount isolator, allowing the spring to contact the vehicle body.

Action: New spring isolators to resolve this concern are currently in limited supply. For critical customer cases, please submit a TA case for assistance with the vehicle repair.