
Reference	SSM72460
Models	XJ / X351
Title	X351 XJ Front Bumper Lower Splitter Trim Coming Adrift
Category	Body
Last modified	30-Jun-2016 00:00:00
Symptom	108000 Ext. Trim/Accessories

Content **Issue:** On some XJ X351 Models, the front lower bumper splitter trim is working loose and / or coming adrift

Cause: Under investigation

Action:

Should you experience this condition, **DO NOT REFIT THE PART.**

Please replace the part & retain the Part, then please submit an ePQR as the part will be required for investigation.

If you are within 100 miles of the Castle Bromwich plant and experience a failure, please contact acampb20@jaguarlandrover.com to possibly arrange a visit from engineering before replacing the part.