

Technical Service Bulletin Number	Revision Level	Date	Group Number
TSB130154			



Technical Service Bulletin

Subject

Peterbilt™ "Legacy" 367, 386, 388, and 389 Chassis with ISX12/15 CM2350 - Engine with Active or Intermittent Fault Code 3596.

Issue

Active or intermittent occurrence of Fault Code 3596 (Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor - Data erratic, intermittent, or incorrect).

It has been determined on 2013 Peterbilt™ Legacy (367, 386, 388, and 389) models that the ground wiring at the DEF pump connector has been incorrectly pinned from the original equipment manufacturer (OEM) factory. Peterbilt™ has issued a field communication to alleviate this condition. This is an OEM-owned repair. Warranty is to be filed through the appropriate Peterbilt™ channels.

Verification

See attached OEM documentation for the field fix. Clear faults and follow troubleshooting tree for FC3596 to make sure the fault was cleared.

Resolution

Please reference the attached Peterbilt™ documentation for resolution in the field. This is an OEM repair and should be filed through the appropriate Peterbilt™ Dealer channels.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Attachments

[Click here to see 131009_attachment.pdf](#)

Document History

Date	Details
2013-10-11	Module Created
2013-10-22	outfile

Last Modified: 22-Oct-2013
