

Technical Service Bulletin Number
--

TSB160112



Technical Service Bulletin

Subject

New Air Intake Manifold Cover

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- L9.3 L105 (**Only** engine serial numbers (ESN) after 90017454)

Issue

Cracks have been observed in select cast air intake manifold covers.

Resolution

- A new welded air intake manifold cover has been released to reduce crack malfunctions.
- For replacement information, see L9.3 L105 Service Manual, Bulletin 4326067. [Refer to Procedure 010-023](#) in Section 10.

Service Parts Availability

Service parts are available. See Table 1.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Cover, Intake Manifold	5311001	No	No	5320447

Service Instructions

Mounting spacer, Part Number 3415598, is **not** to be installed with new air intake manifold cover, Part Number 5320447.

Production Status

Table 2, Production Information		
ESN First	Build Date ¹	Plant
90017454	5-Apr-16	NCI - Guangxi Cummins Industrial Power, Ltd.
¹ Engine build date can be found on the engine dataplate.		

Document History

Date	Details
2016-10-17	Module Created

Last Modified: 19-Oct-2016

Copyright © 2000-2010 Cummins Inc. All rights reserved.