

Technical Service Bulletin

15 Service info: crack on cylinder head cover in area of securing bolt for high-pressure fuel pump - V8TFSI

15 16 29 2045455/1 September 22, 2016.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A8	2013 - 2017	All	Not Applicable
S6	2013 – 2017	All	Not Applicable
S7	2013 – 2017	All	Not Applicable
S8	2015 - 2017	All	Not Applicable
RS 6	2015 - 2017	All	Not Applicable
RS 7	2014 - 2017	All	Not Applicable

Condition

Customer statement:

Crack in the upper area of the cylinder head.

Workshop findings:

A crack appears to be on the cylinder head near the securing bolt of the high-pressure fuel pump.





Technical Service Bulletin

Technical Background

This complaint is not a component-damaging crack. There is excess material on the cylinder head cover from the production process.

Production Solution

Not applicable.

Service

The cylinder head cover does not have to be replaced, this is an optical issue.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All parts and service references provided in this TSB (2045455) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2016 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.