

Technical Service Bulletin



94 Cornering lighting does not work

94 16 79 2043830/2 July 13, 2016. Supersedes Technical Service Bulletin Group 94 number 16-76 dated April 8, 2016 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q5	2013 - 2016	All	With cornering lighting

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised <i>Warranty</i> (Updated claim type)
1	4/8/2016	Initial publication

- The cornering lighting does not work on one side. In the workshop, the halogen bulb for the cornering lighting is determined to be the cause.
- One of the following DTCs may be stored in the vehicle electrical system control module, J519 (address word 09):
 - **DTC 2236** (Right stationary AFS)
 - **DTC 2235** (Left stationary AFS)

Technical Background

Incorrect hardware.

Production Solution

Not applicable.

Service

Replace both halogen bulbs for cornering lighting (on both the affected side and the unaffected side) with part number N10320104.

Technical Service Bulletin



Warranty

Claim Type:	<ul style="list-style-type: none">• 110 up to 6/6• 1EB over 6/6 up to 48/50• If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9423		
Damage Code:	0040		
Labor Operations:	2 halogen bulb remove+reinstall (cornering light)	9423 2010	70 TU
Diagnostic Time:	GFF	0150 0000	Time stated on diagnostic protocol (Max 10 TU)
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
Claim Comment:	As per TSB #2043830/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Part Number	Part Description	Quantity
N10320104	Halogen bulb for static cornering lighting	2

Additional Information

All parts and service references provided in this TSB (2043830) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.