

SSM 46025	Some 2015-2016 Edge vehicle may exhibit a roof opening panel that is slow to close. This may be caused by dirt or debris in the roof opening panel main and/or idler tracks or an issue with the roof opening panel main track assembly or idler track assembly. Engineering is currently investigating this concern. Continue to monitor OASIS for updates.
--------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------