

ATTENTION:

GENERAL MANAGER
 PARTS MANAGER
 CLAIMS PERSONNEL
 SERVICE MANAGER

IMPORTANT - All
 Service Personnel
 Should Read and
 Initial in the boxes
 provided, right.



QUALITY DRIVEN® SERVICE

SERVICE BULLETIN

APPLICABILITY: 2013MY Tribeca
 2012-2013MY Legacy/Outback
 2009-2013MY Forester
SUBJECT: Service Manual Corrections

NUMBER: 18-164-12
DATE: 10/10/12

INTRODUCTION

The purpose of this bulletin is to provide a description of current changes to Service Manuals available via the Subaru Technical Information System (STIS) web site. The tables contained within this bulletin are to be used as guides for becoming aware of the latest changes. We advise you to always refer to the STIS web site when looking for the latest Service information. Printed pages will **not** be made available to update printed Service Manuals.

Paper manuals may have different page numbering then what is reflected below, based on multiple new and revised pages. Please refer to the information contained on the STI web site for all future, update service manual information.

YEAR	MODEL	SECTION	PAGE(S)	DESCRIPTION OF CHANGE
2013	Legacy/ Outback	Engine 1	ME(H4D0)-216	Valve Spring installation note added.
		Body	ES(diag)-48,54	Select Monitor Menu selection corrected.
			KPS(diag)-31	Diagnostic Chart changes.
2012	Legacy/ Outback	Body	ET-36-38	Diagnostics for Steering Satellite Switches changed.
2013	Tribeca	General Information	RM-3	SAE Viscosity Chart changed.
		Engine	LU(H6D0)-3	Recommended Oil Chart changed.
2013	Forester	Engine 1	ME(H4D0)-214	Valve Spring installation note added.
		Body	SB-20	Rear Seat Belt installation caution changed.
2012	Forester	Engine 1	ME(H4D0)-3,216,228	Valve Spring specifications changed.
		Engine 2	EC(H4DOTC)-20	Pressure Control Solenoid Valve testing steps changed.
2011	Forester	Engine 1	ME(H4D0)-3,227	Valve Spring specifications changed.
		Engine 2	EC(H4DOTC)-20	Pressure Control Solenoid Valve testing steps changed.
			EN(H4DOTC)(diag)-214-216	Diagnostic steps for DTC P0453 added.

Continued...

YEAR	MODEL	SECTION	PAGE(S)	DESCRIPTION OF CHANGE
2010	Forester	Engine 1	EC(H4SO)-17	Pressure Control Solenoid Valve testing steps changed.
			EN(H4SO)(diag)-216-218	Diagnostic steps for DTC P0453 added.
		Engine 2	EC(H4DOTC)-20	Pressure Control Solenoid Valve testing steps changed.
			EN(H4DOTC)(diag)-227-229	Diagnostic steps for DTC P0453 added.
2009	Forester	Engine 1	EN(H4SO)-15	Pressure Control Solenoid Valve testing steps changed.
			EN(H4SO)(diag)-211-213	Diagnostic steps for DTC P0453 added.
		Engine 2	EC(H4DOTC)-18	Pressure Control Solenoid Valve testing steps changed.
			EN(H4DOTC)(diag)-225-227	Diagnostic steps for DTC P0453 added.