

---

<b>Reference</b>	SSM72925
<b>Models</b>	F-PACE / X761
<b>Title</b>	Reverse Mirror Dip Return Position
<b>Category</b>	Electrical
<b>Last modified</b>	08-Aug-2016 00:00:00
<b>Symptom</b>	205000 Electrical Accessories

---

**Content****Start VIN: 045000****Issue:**

Exterior door mirror dip position does not always return to previously set position when reverse gear is engaged and then changed back to drive.

**Cause:**

Door Module Software does not allow for the mirror to return back to the previously set position

**Action:**

If a customer reports this concern with their vehicle:

1. Download the latest patch file for SDD (DVD146.005.001 or later)
2. Update all four door modules with the latest software
  - a. Drivers Door Module (DDM)
  - b. Drivers Rear Door Module (DRDM)
  - c. Passenger Front Door Module (PDM)
  - d. Passenger Rear Door Module (PRDM)
3. Test to see if software update has resolved the concern
4. If the concern is not resolved – raise a technical assist case for further diagnosis