

SSM
46291

Some 2017 F-150 and Transit vehicles built on or before 15-Oct 2016 and equipped with a 9.75 axle may exhibit a differential housing cover leak. Before applying the bead of new silicone sealant all surfaces are to be wiped thoroughly with Motorcraft® Metal Surface Prep / ZC-31-B wipes and allowed to dry for a minimum of two minutes. Refer to Workshop Manual (WSM), Section 205-02. Raptor vehicles may also have a differential housing cover stiffening ring, this must be reinstalled during the repair procedure.