

SSM
46210

Some 2010-2016 EPAS equipped vehicles may exhibit steering related noises. The Workshop Manual (WSM) diagnostic procedures have been updated in Section 211-02. When diagnosing and repairing EPAS steering noises use the updated procedures.