
Reference	SSM71995
Models	XK / X150
Title	XK Vehicles - Damaged Armrest Liner
Category	Body
Last modified	15-Oct-2014 00:00:00
Symptom	107000 Interior Trim
Attachments	1Liner damage - PIC 1.pdf 1Removal process - PIC 2.pdf

ContentIssue:

Customers have reported that the Armrest liner is damaged – eg: Corner broken – See pic 1 as an example

Cause::

Poor initial fit / interference contact

Action:

If any damage is found on the armrest liner only, then replace the liner assembly, which is available as a separate part, having the service number XR849520

How to Repair

1. With armrest fully forward raise vertically
2. Hold armrest in position and pull liner firmly from centre to release clips – See pic 2 as an example
3. Fit replacement liner and ensure that all 3 clips engage



