
Reference	SSM72617
Models	F-PACE / X761 F-TYPE / X152 XE / X760 XF / X250 XF / X260 XJ / X351 XK / X150
Title	Coolant Pressure Cap Fitment Process Change
Category	Engine
Last modified	09-Feb-2016 00:00:00
Symptom	402000 Cooling System Concerns
Attachments	IMG_1194.MOV (IMG_1194.MOV)

Content **Issue:** Coolant expansion tank pressure caps leaking causing residue around the tank neck

Cause: Unknown and under investigation

Action: Please ensure when expansion tank pressure caps are removed and refitted, a minimum of 3 audible clicks are heard when refitted. (Video attached)

The workshop manual and owner's handbooks within Topix are currently being updated.