

---

|                      |  |
|----------------------|--|
| <b>Reference</b>     | SSM72596   |
| <b>Models</b>        | XF / X260 (Y03997 → Y00012)  |
| <b>Title</b>         | Rear Suspension Damper Top Mounts  |
| <b>Category</b>      | Chassis  |
| <b>Last modified</b> | 22-Jan-2016 00:00:00   |
| <b>Symptom</b>       | 304000 Suspension System   |
| <b>Content</b>       | <p><b><u>Issue:</u></b><br/>If the vehicle requires a rear suspension damper top mount to be replaced; both top mounts should be replaced as a pair.</p> <p><b><u>Cause:</u></b><br/>To ensure consistent dynamic performance of the vehicle.</p> <p><b><u>Action:</u></b><br/>Replace both rear suspension damper top mounts using the process as detailed in the Workshop Manual, Section 204-02: Rear Suspension.</p> |