
Reference	SSM51717
------------------	----------

Models	XF / X250 XJ / X350 XK / X150
---------------	-------------------------------------

Title	Coolant expansion tank stub pipe leaking up to 2009 MY
--------------	--

Category	Engine
-----------------	--------

Last modified	05-Jan-2015 00:00:00
----------------------	----------------------

Symptom	402000 Cooling System Concerns
----------------	--------------------------------

Content	<p><u>Issue:</u> Coolant expansion tank stub pipe leaking on XJ (X350), XK (X150) or XF (X250) up to the end of 2009 MY.</p> <p><u>Cause:</u> The design of the stub pipe was not adequate and could result in the pipe splitting.</p> <p><u>Action:</u> EPQR have recently been received on this issue. The problem was fixed at the beginning of 2010MY. Unipart stocks have been assured since 2010 MY introduction. EPQR are not required for this issue unless the assured VIN is passed. These VINS are:</p> <ul style="list-style-type: none">• XF R47154• XK B32753• XJ ended at 2009 MY (VIN H30057).
----------------	--