
Reference SSM72914

Models Discovery Sport / L550
Range Rover Evoque / L538

Title Touchscreen goes into re-cycle mode at Ignition on.

Category Electrical

Last modified 12-Aug-2016 00:00:00

Symptom 204000 Instrumentation

Content

Issue:

Vehicles fitted with InControl Touch

Touchscreen goes into re-cycle mode (Re-Boots) when the ignition is switched on.

Cause:

Software bug within the AHU (Audio Head Unit) when the speed dependent volume is set to off.

Action:

1. Do not set the speed dependent volume to off.
2. Set the Speed dependent volume to the minimum setting (This will minimize any volume adjustments audible to the user).
3. Revised software release due early September 2016 (wk36).