



Service Bulletin

American Honda Motor Co., Inc.

SAFETY RECALL

2010-2016 VT750 SERIES - BANK ANGLE SENSOR REPLACEMENT

(Interim Bulletin, final bulletin will be available January 8, 2016)

Honda is launching a Safety Recall of 2010-2016 model year VT750C/CA/CS, VT750C2/C2F/C2S, and VT750C2B motorcycles for a potentially defective bank angle sensor.

Honda has determined that engine vibration may cause the bank angle sensor's wiring to rub on a wire harness connector. Continuous vibration between the bank angle sensor wiring and the wire harness connector may create an open in the bank angle sensor electrical circuit. If an open in the bank angle sensor electrical circuit develops, the engine may stall while riding.

An updated bank angle sensor is available to correct this condition.

Safety Consequence

An engine that stalls while riding increases the risk of a crash.

CUSTOMER NOTIFICATION

During the month of January 2016, Honda will mail a letter to all owners of affected motorcycles informing them that their motorcycle is being recalled for a safety related defect. The customer will be made aware of the safety risk and advised to have a Honda dealer replace the bank angle sensor.

DEALER INVENTORY

Do not sell any un-repaired units.

According to federal law, any affected units in your new inventory cannot be sold or leased until they are repaired with a replacement bank angle sensor, and Honda policy prohibits the sale of new or used un-repaired units.

To search for applicable recalls on a specific unit, refer to *Unit Information* on **iN**.

To manage your affected inventory, use *eResponsibility Report* on **iN**.

See AFFECTED UNITS on Pages 2 and 3.

AFFECTED UNITS

Model		Year	Type	VIN Range	
Shadow Aero	VT750C	2011	A	JH2RC500*BK700001 thru	JH2RC500*BK701715
			AC	JH2RC501*BK700001 thru	JH2RC501*BK700085
		2012	A	JH2RC500*CK800001 thru	JH2RC500*CK800628
			AC	JH2RC501*CK800001 thru	JH2RC501*CK800063
		2013	A	JH2RC500*DK900001 thru	JH2RC500*DK900628
			AC	JH2RC501*DK900001 thru	JH2RC501*DK900062
		2014	A	JH2RC500*EK100001 thru	JH2RC500*EK100471
			AC	JH2RC501*EK100001 thru	JH2RC501*EK100053
	2015	A	JH2RC500*FK200001 thru	JH2RC500*FK201363	
		AC	JH2RC501*FK200001 thru	JH2RC501*FK200146	
	2016	A	JH2RC500*GK300001 thru	JH2RC500*GK300083	
		AC	JH2RC501*GK300001 thru	JH2RC501*GK300008	
	VT750CA	2012	A	JH2RC504*CK700001 thru	JH2RC504*CK700419
			AC	JH2RC505*CK700001 thru	JH2RC505*CK700041
		2013	A	JH2RC504*DK800001 thru	JH2RC504*DK800418
			AC	JH2RC505*DK800001 thru	JH2RC505*DK800042
		2014	A	JH2RC504*EK900001 thru	JH2RC504*EK900313
			AC	JH2RC505*EK900001 thru	JH2RC505*EK900036
	VT750CS	2013	AC	JH2RC508*DK200001 thru	JH2RC508*DK200050
		2014	AC	JH2RC508*EK300001 thru	JH2RC508*EK300027
2015		AC	JH2RC508*FK400001 thru	JH2RC508*FK400041	
2016		AC	JH2RC508*GK500001 thru	JH2RC508*GK500009	
Shadow Spirit	VT750C2	2012	A	JH2RC530*CK400001 thru	JH2RC530*CK401135
			AC	JH2RC531*CK400001 thru	JH2RC531*CK400112
		2013	A	JH2RC530*DK500001 thru	JH2RC530*DK500314
			AC	JH2RC531*DK500001 thru	JH2RC531*DK500020
		2014	A	JH2RC530*EK600001 thru	JH2RC530*EK600381
			AC	JH2RC531*EK600001 thru	JH2RC531*EK600039
	VT750C2F	2012	A	JH2RC534*CK500001 thru	JH2RC534*CK500822
			AC	JH2RC535*CK500001 thru	JH2RC535*CK500081
		2013	A	JH2RC534*DK600001 thru	JH2RC534*DK600293
			AC	JH2RC535*DK600001 thru	JH2RC535*DK600026
		2014	A	JH2RC534*EK700001 thru	JH2RC534*EK700282
			AC	JH2RC535*EK700001 thru	JH2RC535*EK700029
	VT750C2S	2013	AC	JH2RC53G*DK100001 thru	JH2RC53G*DK100022
		2014	AC	JH2RC53G*EK200001 thru	JH2RC53G*EK200019

Model		Year	Type	VIN Range	
Shadow Phantom	VT750C2B	2010	A	JH2RC537*AK000002 thru	JH2RC537*AK001481
			AC	JH2RC538*AK000003 thru	JH2RC538*AK000122
		2011	A	JH2RC537*BK100001 thru	JH2RC537*BK101710
			AC	JH2RC538*BK100001 thru	JH2RC538*BK100160
		2012	A	JH2RC537*CK200001 thru	JH2RC537*CK201700
			AC	JH2RC538*CK200001 thru	JH2RC538*CK200210
		2013	A	JH2RC537*DK300001 thru	JH2RC537*DK302236
			AC	JH2RC538*DK300001 thru	JH2RC538*DK300304
		2014	A	JH2RC537*EK400001 thru	JH2RC537*EK400845
			AC	JH2RC538*EK400001 thru	JH2RC538*EK400105
		2015	A	JH2RC537*FK500001 thru	JH2RC537*FK502563
			AC	JH2RC538*FK500001 thru	JH2RC538*FK500337
		2016	A	JH2RC537*GK600001 thru	JH2RC537*GK600091
			AC	JH2RC538*GK600001 thru	JH2RC538*GK600009