

**October 9, 2015**

01752 Version 3

**SRS Unit Collection****This bulletin has been cancelled because the collection is now complete.**

If you did the collection in Service Bulletin 15-026 on or before October 8, 2015 (RO date), use the Warranty Claim Information provided below.

**WARRANTY CLAIM INFORMATION**

<b>Operation Number</b>	<b>Description</b>	<b>Flat Rate Time</b>	<b>Defect Code</b>	<b>Symptom Code</b>	<b>Template ID</b>	<b>Failed Part Number</b>
7511B4	Repair Procedure A - Inspect the vehicle, replace the SRS unit, and remove the noise suppressor. (includes resetting power window, idle learn, and OPDS initialization)	1.2 hrs	5YT00	JP500	15-026A	77960-S0X-L81
7511B3	Repair Procedure B - Inspect the vehicle and replace the SRS unit. (includes resetting power window, idle learn, and OPDS initialization)	0.8 hr	5YT00	JP500	15-026B	77960-S0X-L81

**CUSTOMER INFORMATION:** The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.