Special Service Message

NOTE: A Special Service Message is a formal communication issued by Land Rover and carries the same importance of a Technical Service Bulletin. An SSM is a quick method of communicating "Need To Know" information to the technical service community. SSM's may be issued in advance of a technical bulletin or may be the only communication on a given topic. All information contained in Land Rover technical communications are intended for use by trained, professional technicians with the knowledge, tools, and equipment required to complete the procedure correctly and safely. It informs the Technicians of conditions that may occur on some vehicles, or provides information that could assist in correct vehicle and diagnostic service.

SSM 72337 - HD Radio Sub- Channels Missing

Models: LC - Discovery Sport

Engineer Martucci Gregory

Name:

Last 13-07-2015 21:14:31

Modified:

Category: Electrical

Symptom: 207000 Entertainment Systems

Content: Issue: Customer may complain that they cannot tune

to the HD radio sub-channels with HD radio turned on.

Cause: Audio Head Unit software concern.

Action: Should a customer complain that they cannot tune to an HD radio substation with HD radio turned on, program the Audio Head Unit (Low Line) as existing

using SDD DVD 142 or later.

Jaguar Land Rover Limited 2000 - 2015 (Rel. 2620A)