

Special Service Message

NOTE: A Special Service Message is a formal communication issued by Land Rover and carries the same importance of a Technical Service Bulletin. An SSM is a quick method of communicating "Need To Know" information to the technical service community. SSM's may be issued in advance of a technical bulletin or may be the only communication on a given topic. All information contained in Land Rover technical communications are intended for use by trained, professional technicians with the knowledge, tools, and equipment required to complete the procedure correctly and safely. It informs the Technicians of conditions that may occur on some vehicles, or provides information that could assist in correct vehicle and diagnostic service.

SSM 72338 - Park Assist Module Programming

Models : LG - Range Rover (All
New) - L405
LW - Range Rover Sport
- L494

Engineer Martucci Gregory
Name :

Last 13-07-2015 16:18:58

Modified :

Category : Electrical

Symptom : 206000 Warning Indicators

Content : Models Affected:

15MY Range Rover / L405

15MY Range Rover Sport / L494

Issue:

After programming the Park Assist Module, Technicians have reported that the system is no longer operational and may store U2300-XX central configuration codes.

Cause:

Park Assist Module (PAM) software concern.

Action:

Do not attempt to program the PAM for any concern. A new software is being developed and a further communication will be issued in due course. If the PAM requires replacement please contact the Technical Helpline before programming is performed.