
Reference	SSM72607
Models	Discovery Sport / L550
Title	InControl Touch - Cannot Switch SDARS Channels
Category	Electrical
Last modified	02-Feb-2016 00:00:00
Symptom	207000 Entertainment Systems
Content	<p><u>Issue:</u> InControl Touch cannot Switch SDARS Channels.</p> <p><u>Cause:</u> Software error with the AHU (Audio Head Unit).</p> <p><u>Action:</u> Please ensure that SDD has DVD 144 Patch 5 is installed.</p> <ul style="list-style-type: none">• Using SDD perform software update to the AHU.