

---

<b>Reference</b>	SSM72874
<b>Models</b>	Discovery Sport / L550 Range Rover Evoque / L538
<b>Title</b>	L538 & L550 RR Evoque and Discovery Sport windscreen wiper issues
<b>Category</b>	Electrical
<b>Last modified</b>	19-Jul-2016 00:00:00
<b>Symptom</b>	202000 Wiper/Washer System

---

**Content**      Issue: Retailers are replacing front windscreen wiper motors due to park position concerns.

Cause: Motors returned are of no fault found.

Action: Please review TOPIx Workshop manual prior to relpacing the motors:

- 501: Body and Paint
- 501-16: Wipers and Washers
- Diagnosis and Testing
- Wipers and Washers

Please pay particular attention to winter park mode settings.

If the issue persists, please raise a TA. For UK vehicles, please raise a TA and contact Ian Cavanagh [icavanag@jaguarlandrover.com](mailto:icavanag@jaguarlandrover.com) where a visit may be required.