
March 4, 2017

05858 Version 2

2013–17 Accord: Judder from the Torque Converter Lock-Up Clutch

This bulletin is replaced by 17-017, *2013–17 Accord: Judder from the Torque Converter Lock-Up Clutch*

All vehicles affected by this bulletin were superseded to 17-017.

If you did service bulletin 16-061 on or before March 4, 2017, make sure to use the WARRANTY CLAIM INFORMATION provided below to file a claim.

WARRANTY CLAIM INFORMATION

The normal warranty applies.

| Operation Number | Description | Flat Rate Time | Defect Code | Symptom Code | Template ID | Failed Part Number |
|------------------|---|----------------|-------------|--------------|-------------|--------------------|
| 2181BP | ATF flush procedure. Includes test-drive. | 1.4 hrs | 01102 | 03505 | 16-061A | 26000-5J7-305 |

Skill Level: Repair Technician

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.