

U.S. Department of Transportation

National Highway Traffic Safety Administration

August 2, 2022

Mr. Greg Gunther Department Manager VCA Mercedes-Benz USA, LLC 13470 International Parkway Jacksonville, FL 32218

1200 New Jersey Avenue SE Washington, DC 20590

NEF-107ES 22V-533

Subject: Misrouted Harness May Corrode and Short-Circuit

Dear Mr. Gunther:

This letter serves to acknowledge Mercedes-Benz USA, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MERCEDES-BENZ/AMG CLS53/2019-2021 MERCEDES-BENZ/AMG E53/2019-2023 MERCEDES-BENZ/AMG GT43/2021-2023 MERCEDES-BENZ/AMG GT53/2019-2023 MERCEDES-BENZ/CLS450/2019-2023 MERCEDES-BENZ/E450/2021-2023

Mfr's Report Date: July 22, 2022

NHTSA Campaign Number: 22V-533

Components:

ELECTRICAL SYSTEM:WIRING

Potential Number of Units Affected: 27.330

Problem Description:

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2021-2023 AMG GT43, E450 Cabriolet, E450 Wagon, E450 Coupe, 2019-2023 AMG E53, E53 Coupe, E53 Cabriolet, AMG GT53, CLS450, and 2019-2021 AMG CLS53 vehicles. The transmission wiring harness may be misrouted, which can expose the electrical connector to corrosion, and result in an electrical short-circuit.

Consequence:

An electrical short-circuit can increase the risk of a fire.

Remedy:

Dealers will inspect and repair the electrical connector, as necessary. Dealers will also reroute the harness and install an additional bracket. All repairs will be performed free of charge. Owner notification letters are expected to be mailed September 20, 2022. Owners may contact MBUSA customer service at 1-800-367-6372.



Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Mercedes-Benz USA, LLC's contact for this recall will be Emily C. Smith who may be reached by email at emily.c.smith@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Chief, Recall Management Division Office of Defects Investigation

Office of Defects investigation

Enforcement

