

RECALLS



< Enter New VIN

Find A Dealer >

VEHICLE: 2022 F-150 LIGHTNING VIN: <17 Character VIN>

1 RECALLS*

RECONFIGURE THE BODY CONTROL MODULE WITH UPDATED AS-BUILT DATA

Details ^

Recall Incomplete

Issue Date

2022-06-24

Description

ON YOUR VEHICLE, THE TIRE PRESSURE MONITORING SYSTEM TPMS LIGHT IN YOUR VEHICLES INSTRUMENT CLUSTER MAY NOT ILLUMINATE AS QUICKLY AS INTENDED IF THE TIRE PRESSURE DROPS.

Safety Risk

LOW TIRE PRESSURE MAY LEAD TO POOR VEHICLE HANDLING AND A POSSIBLE LOSS OF VEHICLE CONTROL, INCREASING THE RISK OF A CRASH.

Remedy

THE BODY CONTROL MODULE BCM IN YOUR VEHICLE NEEDS TO BE UPDATED TO CORRECT THE TIRE PRESSURE MONITORING SYSTEM ALERT POINTS. WE RECOMMEND CHECKING YOUR VEHICLES TIRE PRESSURE AND ENSURE IT MATCHES THE FIGURES PROVIDED ON THE LABEL LOCATED INSIDE THE DRIVER-SIDE FRONT DOOR JAMB. IN ADDITION TO YOUR DEALER BEING ABLE TO UPDATE YOUR VEHICLE NOW, FORD WILL ALSO HAVE THE REMEDY AVAILABLE THROUGH A FORD POWER-UP SOFTWARE UPDATE WITHIN 30 DAYS. FORD WILL NOTIFY YOU WHEN IT IS AVAILABLE.

Campaign/NHTSA#

22C15/22V453

LIVE CHAT