1301 Stahley Drive
Building #42
Nappanee, IN 46550

Newmar Corporation Warranty Department

Dealer Svc. 866-290-5371
Customer Svc. 800-731-8300

Recall Service Bulletin

Date Issued	Model Year(s) Affected	RSB #
4/26/2018	2018	519

Model

Bay Star Sport	☒	Ventana	☒	Essex	☒
Bay Star	☒	Dutch Star	☒	King Aire	☒
Canyon Star	☒	Mountain Aire	☒	New Aire	☒
Ventana LE	☒	London Aire	☒	Other	☐

Description

Newmar Corporation has decided that a defect relating to motor vehicle safety exists in specific motorhomes. Recall NHTSA 18V 236, TC 2018-182.

On certain motorhomes, there may be loose electrical connections in the breaker box that were not properly tightened. A loose power connection may cause a buildup of heat at the connection, potentially increasing the risk of overheating or a fire causing injury and/or damage to property.

Correction: Dealers will inspect the electrical connections in the breaker box and repair as necessary.

Affected Units: Refer to the attached population list for specific coach and VIN numbers.

Recommended Action

Inspect the breaker box. Torque the electrical connections to the specified torque listed on the breaker box cover. Submit the claim.

If the breaker box and/or wiring are damaged from heat buildup, submit photos and contact your Newmar Service Account Manager for authorization of additional labor time and/or parts.

Flat Rate Code: 18V 236 **Labor time: .3 hr.**

Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.

If you have any questions regarding this R.S.B., please contact a Warranty Service Representative at Newmar Corporation.