Peterbilt
A PACCAR COMPANY

SB-10055902-5053

Repair Notice

414-2

Section

CAB

Description

Model 587 Fog Lamp Functionality Enabled

Release Date

5/2/2014

Introduction

Certain Model 587 vehicles were manufactured with the fog lamp functionality disabled. Peterbilt has software updates available that will enable the functionality of the fog lamps.

Resolution

Update the CECU software to enable the fog lamp functionality.

Warranty

The SIR system will indicate chassis involved in this field repair with the designator for 414-2. If the vehicle is affected and is shown to have an open campaign, please complete the work and file a quick claim "*414-2*".

Parts

There are no parts for the campaign, only software updates.

Labor

Peterbilt wdll reimburse the dealer 0.3 hours labor for reflashing the CECU to correct the fog lamp defect.

Procedure

Reflash the CECU software.

- Use ESA version 4.4.2.153 for the latest updates
- Update software to P30-1014-108 for Model 587
- Test functionality of fog lamps with high beam headlights. Fog lamps must turn off and stay off when high beam headlights are activated.

Attachments

414-2 Chassis List