November 7, 2016

A PACCAR COMPANY

[First VIN]
Customer Name
Address
City, State Zip

Subject: Field Repair 716-1: Model 579/567 Watson & Chalin Lift Axle Frame Bracket

Dear Peterbilt Customer,

Your vehicle (listed on the back of this letter) is eligible for a campaign to inspect and repair the lift axle frame brackets or replace as needed.

The problem is…	Lift axle frame bracket cracking
Correction…	Inspect and replace affected brackets
What you must do …	Contact your Peterbilt dealer to schedule an appointment

Please contact a Peterbilt dealership to schedule an appointment for this work. If you've already had this work performed, please disregard this letter. You can find the nearest Peterbilt dealer at Dealer Locator on the website www.Peterbilt.com.

When contacting your selected Peterbilt dealer, refer to campaign **716-1** and the VIN listed on this letter. The upgrade could take up to **12 hours** and there will be no charge to you if completed within Standard Warranty (includes Extended Warranty) or for upgrades completed by **11/1/2017**, whichever is greater.

We apologize for this inconvenience but ask for your cooperation to ensure continued satisfaction with Peterbilt products.

Thank you,

Douglas K. Gunter

Doug Gunter
Director of Warranty
Peterbilt Motors Company

SAMPLE

SAMPLE