iKNOW Knowledge Base

Countries:	UNITED STATES	**Document ID**:	IK2700090
Availability:	ISIS, Bus ISIS, FleetISIS, Body Builder, NotSIR	**Revision**:	39
Major System:	EZ-TECH SUPPORT	**Created**:	10/17/2014
Current Language:	English	**Last Modified**:	6/5/2017
Other Languages:	NONE	**Author**:	Fausto Coloma
Viewed:	6917		

Less Info

Hide Details   Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
🔗	🔗	View My Bookmarks	⭐	🖨	💬	👍 25	👎 2

Title: OnCommand EZ-Tech Download Center

Applies To: OnCommand EZ-Tech

CHANGE LOG

Dealers: Please refer to the change log text box below for recent changes to this article..

> 06/05/2017 - Added NEW drivers for Nexiq USB-Link 2 v2.6.0.2
> 05/23/2017 - Added NEW releases for DLB 15577 Db:250, NED v2.53, NavKal v45.38, Meritor Wabco 12.4.1.0 and CPA 8.8.21.1.
> 05/02/2017 - Added NEW releases for Adobe Flash Player 25.0.0.148, Adobe Shockwave Player v12.2.8.198, OpenOffice v4.13, Noregon drivers 4.2.6284.0 and Cummins INLINE 6 drives.
> 03/29/2017 - Added NEW release for Navistar EZ-Tech Launcher v4.3.0.5, Allison DOC Premium 2017 and EDiTH S4V4 (Espar Heaters).

Welcome to the

OnCommand™ Eztech

Download Center

DESCRIPTION

The software update process is being done automatically by the "Symantec Altiris Client" on your computer.   When the update is too large to be pushed out, a SPLASH SCREEN will appear on your computer to let you know that an update is needed also information on how to get the update will be displayed as well.

If the update is considered CRITICAL, the splash screen will continue to show up until you perform the update process on your EZ-Tech computer.

If you have not gotten an update needed through the Altiris Agent then you can download the update on demand using the links provided below.

	Software	Last Updated on	Description	File Name	Link #2
A1	EZ-Tech Critical Updates Reporting Tool	06/02/2017 NEW!! Database Update	PC Updates	This little program will create a report of the critical updates needed by your OnCommand EZ-Tech. IMPORTANT NOTE: This file was compressed and password protected. Please unzip the file and use the password: "navistar" (All	Click Here

				lowercases & without the quotes).	
B1A	Bendix ACom version 6.12.2.2 Windows 7 only!	02/14/2017	Brake System	This program will replace your current version of Bendix ACom software to version 6.12 Products Supported by this version: Click HERE	Click Here
B2A	Meritor Wabco Toolbox version 12.4.1.0 Windows 7 only!	05/23/2017 NEW!!	Brake System	This program will upgrade your current installation of Meritor Wabco 11.x on your computer to the NEW version 12.4. Upgrading to the NEW version 12.4 will not remove the license on your current installation. The license will remain active after this upgrade. IMPORTANT NOTE: The self-installer program needs to perform several operations to install the software including logging off and on from your computer. Please follow the instructions on screen and do NOT interrupt the installation process. Wait until the completion notice.	Click Here
B5A	HPB Programmer v3.20	10/13/2013	Brake System	This program is needed to program HEBF0001.	Click Here
B5B	HPB Programmer v3.31	09/05/2014	Brake System	This program is needed only if programming HEAB0004 or workhorse programming.	Click Here
E1	Navistar Engine Diagnostics (NED) Release v2.53	05/23/2017 NEW!!	Engine	Navistar will be discontinuing sales and future development of ServiceMaxx™J1939 (Pro and Lite). With the sunset of ServiceMaxx J1939, Navistar Engine Diagnostics (NED) will be the direct replacement and will cover all J1939 MaxxForce® and Navistar® engine diagnostics.	Click Here

E2	DLC Fleet Tool expires 12/15/17	02/14/2017	Engine	This program will install on your computer's desktop the DLC Fleet Tool. This tool will NOT work on engines 2010 emission complaint. On those cases you will need Servicemaxx. Nothing was changed from the previous release, only the expiration date.	Click Here
E4	NavKal Software release v45.38	05/23/2017 NEW!!	Engine	OFFICIAL RELEASE: This program will install the NEW NavKal v45.38 on your OnCommand EZ-Tech computer. This program is licensed to you for 5 years from the original shipping date of the computer. Normally, you should get the license key if your computer is connected to the internet. If you don't have a license, please contact our EZ-Tech Support Group at 1-800-336-4500. Make sure your computer is connected to the internet while installing the software.	Click Here
E8	CPA Registration Reset Software	12/17/2012	Engine	This little program will delete the current registration of the CPA software. The next time you open the CPA application, you will need to fill in the Dealer information again. Make sure you do this or you will have problems getting WAC codes.	Click Here
E9	CPA Removal Tool	07/01/2014	Engine	This application will remove completely all versions of the CPA software from your computer. After running this tool you will need to install the FULL version of the CPA software using the link on E11B.	Click Here
E11A	Cylinder Performance Analyzer Software (CPA) v8.8.21.1 **UPGRADE** Installation	05/23/2017 NEW!!	Engine	This program will UPGRADE your current CPA versions 4.x.x.x, 5.x.x.x, 6.x.x.x or 7.x.x.x to the NEW 8.8.21.1. WARNING - PLEASE READ THIS! For more information on how to install this software please check: a) Installation Instructions (PDF): Here b) If you don't know what version of CPA you have on your computer... Please run the following tool: Here Note: You will find the download links on the Installation Instructions document provided on (a)	
E11B	Cylinder Performance Analyzer Software (CPA) v8.8.21.1 **FULL** Installation	05/23/2017 NEW!!	Engine		

				This FULL installation package is needed only if you are running older versions of the software: 2.0.149, 3.0.16 or 3.0.19 otherwise please use the UPGRADE package for a faster installation. WARNING - PLEASE READ THIS! For more information on how to install this software please check: a) Installation Instructions (PDF): Here b) If you don't know what version of CPA you have on your computer... Please run the following tool: Here Note: You will find the download links on the Installation Instructions document provided on (a)	
E15J	ServiceMaxx J1708 v43.26.201512041513 ServiceMaxx J1708 Supported Engines o Pre-MaxxForce Engines • I63BX: 3 Box I6 (1994 - 1997) • V83BX: 3 Box V8 (1994 - 1997) • i308: DLC I6 (1998 - 2004) • T444E: DLC V8 (1998 - 2004) • I313: DLCII I6 (2005 - 2006) • V128: DLCII V8 (2005 - 2006) • V126: DLCII V6 (2005 - 2006)	12/10/15	Engine	This package will install the NEW ServiceMaxx J1708 for legacy engines.	Click Here
E17	EZ-Tech Navistar Launcher v4.3.0.5 Windows 7 only!	03/29/2017 NEW!!	GUI Replacement	This package will install the NEW Navistar Launcher ONLY on your supported EZ-Tech computer. Also the package will remove the old GUI from startup and at the end of the installation it will allow the user to view the User's Guide. The Navistar Launcher "Health Report" feature will NOT work with Movimento or IC4 adapters. IMPORTANT NOTE: This NEW version may require the user to enter the Dealer Information correctly to proper register the software with the EZ-Tech and prevent problems during the Health Reports uploading process.	Click Here
E18	EZ-Tech Navistar Launcher **Removal** Tool	03/13/2015	GUI Replacement	This package will REMOVE the Navistar Launcher application and the	Click Here

				registration information from your computer. **IMPORTANT NOTES:** Please use this package only when you cannot use the Navistar Launcher due to a .NET error. After using this tool, you will need to install the application again using the links on E17.	
E19	Diamond Logic Builder Fleet (Offline version) Version: 15520 Database: 224 Date: 05/04/2016	05/26/2016	Body Builder	This package will install the NEW version of DLB software on your EZ-Tech. The new DLB version does not rely on Java Web Start when launched. It includes an embedded version, so say good bye to the "Unable to Launch" error message. To install this package just double click the executable and wait for the completion message. **IMPORTANT NOTE:** This new version of DLB supports Java 7. However, other software still requires the use of Java 6u27. Please do not update the version of Java from your computer at this time.	Click Here
E19A	Diamond Logic Builder (Online version) Version: 15577 Database: 250 Date: 05/23/17	05/23/17 NEW!!	Body Builder	This program will install the FULL online version of DLB on your OnCommand_EZ-Tech. Normally, you should get the license key if your computer is connected to the internet. If you don't have a license, please contact our EZ-Tech Support Group at 1-800-336-4500.	Click Here
E20	Cummins DESA (Dynamic Engine System Analysis) Version: 1.7.0	11/01/2016	Engine	This program will install the software DESA by Cummins on your EZ-Tech computer. Please install the software if requested by Cummins Tech Service to diagnose the Aftertreatment System. **IMPORTANT NOTE:** The DESA application requires a valid license to work. The license is available directly from Cummins. Open the application and click on "Help" for additional information on how to request a new or replacement license.	FULL Installer (459MB) Click Here UPGRADE Installer (12MB) Click Here
V1	Movimento NavLink- NavCoM 1.6.4	02/03/2014	Vehicle Adapter	This program will update your computer with the latest drivers 1.6.4 for the Movimento adapter. If you	Click Here

				already have this version, the program will "repair" the current installation to ensure that the drivers are installed correctly. Please be advised that this vehicle adapter **will NOT work** with the Navistar Launcher to retrieve the Health Reports.	
V2	Nexiq USB-Link drivers 9.6.0.2 Windows XP or 7!	12/15/2016	Vehicle Adapter	This program will update your drivers for the Nexiq USB-Link 1 vehicle adapter. IMPORTANT NOTES: (1) The new version 9.6.0.2 is working fine with ServiceMaxx and Diamond Logic Builder. This version is the latest available from Nexiq.	Click Here
V2-1	Nexiq USB-Link 2 drivers 2.6.0.2 Windows 7 only!	06/05/2017 NEW!!	Vehicle Adapter	This program will install the drivers for the NEW Nexiq USB-Link 2 adapter. Please be advised that the Nexiq USB-Link 2 is NOT compatible with Automatic Upgrade at this time. IMPORTANT NOTES: (1) These drivers are needed only if you have the USB-Link 2 adapter (See Picture) (2) The same computer can use either adapter. These drivers will not remove the drivers for the USB-Link 1 adapter.	Click Here
V3-2	Dearborn DPA4+ version 6.05 (CD version)	09/23/2013	Vehicle Adapter	Dearborn Legacy DPA 4+ Installation CD (DG121032)	Click Here
V4	Dearborn DPA5 USB	05/23/2016	Vehicle Adapter	Dearborn DPA 5 Multi USB version 2.03	Click Here
V5	Noregon DLA+ 2.0 and DLA+ Wireless 2.0 Drivers	05/02/2017 NEW!!	Vehicle Adapter	Noregon DLA+ 2.0 Newest Adapters 4.0.6284.2	**DLA+ 2.0:** Click Here **DLA+2.0 Wireless:** Click Here
V5a	Noregon				

	DLA+ Adapter	05/02/2017 NEW!!	Vehicle Adapter	Noregon JPRO DLA+ Installer version 4.0.6284.2	Click Here
V5b	Noregon DLA+ PLC Adapter	05/02/2017 NEW!!	Vehicle Adapter	Noregon JPRO DLA Plus PLC Installer version 4.0.6284.2	Click Here
V5c	Noregon DLA+ Wireless Adapter	05/02/2017 NEW!!	Vehicle Adapter	Noregon JPRO DLA Plus Wireless Installer version 4.0.6284.2	Click Here
V6	Cummins INLINE 5 driver 5.6.5.4	08/07/2013	Vehicle Adapter	This program will install the latest drivers 5.6.5.4 for the Cummins INLINE 5 adapter on your computer.	Click Here
V7	Cummins INLINE 6 driver 6.9.0.0	05/02/2017 NEW!!	Vehicle Adapter	Please run the Cummins Updates Manager to receive the latest version of the INLINE 6 drivers.	
V8	Cummins INLINE 7 driver 2.3.0.0	11/01/2016	Vehicle Adapter	This application will install the latest drivers for Cummins INLINE 7 USB vehicle adapter.	Click Here

T1	Allison DOC Launcher	06/13/2013	Transmission	This application will launch the Allison DOC program as an administrator so you will be able to install the updates by yourself.	Click Here
T2	Allison DOC **17.0** Installer (645MB download)	03/20/2017 NEW!!	Transmission	This program will install the NEW Allison DOC software version 14 on your EZ-Tech. IMPORTANT INFORMATION - PLEASE READ CAREFULLY Having a valid license for Allison DOC 10+, 11+, 12+ or 13+ does not provide you with upgrade rights for Allison DOC 14+. A new license will be required (Upgrade License).	Click Here
T6	Allison DOC Software **Remover** (All versions)	04/02/2015	Transmission	This program will remove Allison DOC versions 9, 10, 11, 12 & 13 from your EZ-Tech. It will NOT remove the Allison DOC Advanced Help application.	Click Here
T7	EATON ServiceRanger 2.8	01/17/2014	Transmission	This program will update your current version of ServiceRanger 2.6 to 2.8. This program is still needed for old transmissions.	Click Here
T8	ServiceRanger 4.0 Tool Program Updates	03/26/2014	Transmission	This tool will help you to install updates on your EZ-Tech computer without admin rights. Just run the tool and follow the instructions on the screen. After you install this program, you will always be able to update ServiceRanger 4.0 using the "icon" located on the system tray (next to the clock).	Click Here
T9	ServiceRanger Version: 4.2.1187.0	03/20/2017 NEW!!	Transmission	IMPORTANT INFORMATION - PLEASE READ CAREFULLY This package will install the NEW SR 4.0 from Eaton on your EZ-Tech computer. Please be advised that ServiceRanger 3.0 is no longer available since 03/26/2014.	Click Here

T10	ServiceRanger 4.0 - Uninstaller ONLY	07/07/2015	Transmission	This application will remove the ServiceRanger 4.0 from your computer. This step is necessary to ensure a clean installation of version 4.0.2331.0 or while directed by tech support. Important Note: Be advised that by removing the software you will removing also the license/activation of it. Before you use this app, make sure you have all necessary information to reactivate the software with Eaton. Navistar do not keep records about software activations.	Click Here
M1	EDiTH version S4V4	03/20/2017 NEW!!	ESPAR Heaters	The EDiTH software is needed to troubleshoot the ESPAR heaters installed on certain vehicles running on extremely cold weather.	Click Here
M2A	Midtronics EXP HD IR Reader v1.4	06/08/2015	Battery Tester	This program will install the new version 1.4 required for the NEW 2015 Battery Tester. WARNING: This NEW version is NOT compatible with the older model of the Battery Tester. Please install this update only if directed by Tech Services.	Click Here
M5	Webasto WTT v3.1 Webasto Feel the Drive	09/09/2015	Webasto Heaters	This software is needed to troubleshoot Webasto Thermo & Heaters equipment. Version 3.1 is for Windows 7 only. To download the User's Guide click HERE.	Click Here
U0	Adobe Flash Player 25.0.0.148 Adobe Flash Player	05/02/2017 NEW!!	Utilities	Run this program to install the latest version of Adobe Flash Player on your computer.	Click Here
U0A	Adobe Shockwave Player v12.2.8.198 Adobe Shockwave Player	05/02/2017 NEW!!	Utilities	Run this application to install the latest version of Adobe Shockwave Player on your computer. This application is used to display certain training videos from Cummins.	Click Here
U2	Apache OpenOffice v4.13 The Free and Open Productivity Suite Apache OpenOffice™ 100,000,000+ Downloads!	05/02/2017 NEW!!	Utilities	This program will install the complete suite for OpenOffice product: Writer (Word), Calc (Excel), Impress (PowerPoint), Draw, Base & Math. The software is compatible with other major office suites. Important Note: The software is not supported by Navistar. It is supported by the software developer. More info: www.openoffice.org	Click Here

| U5 | Internet Explorer 11
 Windows 7 only! | 08/17/2015 | Utilities | This will upgrade your current version of Internet Explorer to the latest version 11. Your computer will need to be connected to the internet to perform this upgrade.

 The auto-installer will complete the installation after the computer restarts. Please wait for the script finalizes the optimization for IE11. | Click Here |

Please e-mail suggestions or concerns about this article to: fausto.coloma@navistar.com

⌃ **Hide Details**   **Feedback Information**

Viewed: 6916

Helpful: 25

Not Helpful: 2

No Feedback Found