Diagnostic Application - Windows Internet Explorer

File   Edit   View   Favorites   Tools   Help

http://localhost:8080/pat2_launch.action?candidateId=DATALOGGER&abortAction=pat2_completed

SDD   TOPIx   GCM

Bulletins   Workshop Manual   Wiring Diagrams   Electrical Reference Library

Session   Selected Symptoms   DTCs   Recommendations   Extras   Service Functions

Vehicle   Settings   Sessions

Keyless vehicle input switch status - Front left unlock pull switch (KVM)   0 (OFF)

Keyless vehicle input switch status - Front right unlock pull switch (KVM)   0 (OFF)

Keyless vehicle input switch status - Rear left unlock pull switch. (KVM)   0 (OFF)

Keyless vehicle input switch status - Rear right unlock pull switch. (KVM)   0 (OFF)

Keyless vehicle input switch status - Front right unlock pull switch

Andy Roberts - Discovery Sport (L550) 715271 - 17 Aug 2017 12:07 (150.04 v.275) - NGI:-/-/-/004.03/005.01/

Done   Trusted sites | Protected Mode: Off   The JLR VCI is connected.   100%

PCU Diagnostics > Remote Function Actuation [RFA] > Live data

Remote keyless input switch status->Right Front ... Full Switch [A113] - Off

Remote keyless input switch status->Right Front Unlock Full Switch [A113] - On

Remote keyless input switch status->Left Front Unlock Full Switch [A113] - Off

Remote keyless input switch status->Left Front Unlock Full Switch [A113] - On

Time/S

Continue

Pause

Back

Forward

Jaguar F-Pace X761 (DoIP)   VIN SAD GA2AX1JA040100   Model year 2018   Odometer 2540 mi

12.1 V