NEW DIAGNOSTIC SOFTWARE AVAILABLE FOR DOWNLOAD TRIUMPH ▽

Notice Information

Ref	12378
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Service Leader / Advisor, Accounts / Admin
Subject:	Service/Technical

TOL NOTICE (US&CAN) – October 18, 2019   **TOL**
Ref. # 12378-SVC

New Diagnostic Software Available for Download

Diagnostic software version **2019-5.1** is now available to download. Dealers should download this update from your Triumph Diagnostic Software page under the Service/Technical menu and begin using immediately.

- Please ensure all new bikes have the latest software downloaded at PDI.
- Please ensure all bikes being serviced have the latest software downloaded.
- Please ensure all relevant staff are informed of this update.

**PASSWORD CHANGE: New Password (case sensitive): Moto219

Note: When running the diagnostic software **2019-5.1** for the first time following installation, you will be prompted to enter your dealer company details before being able to proceed.

SUMMARY OF CHANGES:

1	**New Software Functionality:**	None
2	**Engine ECM Calibrations:**	None
3	**Chassis ECM Calibrations:**	None
4	**Instrument ECM Calibrations:**	None
5	**Keyless ECM Calibrations:**	None
6	**New ECU Unlock Codes:**	None
7	**Calibration Description Corrections:**	None
8	**Bug Fix(es):**	This update resolves a bug reported in 2019-5 relating to connection errors when entering engine ECM diagnostics on older models fitted with KHE and KEN4 ECMs.

If you have any questions, please contact Triumph Customer Support at (888) 284-6288.