INFORMATION

Subject: Information on No Malfunction Indicator Lamp (MIL) Illuminated, Ignore These DTCs if Set in History

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	**to**	**from**	**to**		
Cadillac	CT4	2020	2020	—	—	All	All
	CT5						

Involved Region or Country	North America, Germany, Korea, Middle East, China
Condition	Though customers do NOT see any MIL illuminated, technicians may comment on finding DTCs set in History. The DTCs may include any number of DTCs listed in the table below.
Cause	• If any of the DTCs listed in the table below are **set in History, and there is NO customer concern**, they have no customer impact and should be ignored. • If these DTCs are **Currently set**, do NOT ignore them but diagnose as normal.
Correction	A correction will be released at a later date.

DTCs to Ignore

Module	DTC #	DTC Long Name
Remote Control Access Sensor	U1135 00	Lost Communication with Virtual Key Sensor - One
Remote Control Access Sensor	U1137 00	Lost Communication with Virtual Key Sensor - Three
Telematic Control Module	B1B2F 00	Radio Audio Video Communication Lost Diagnostic Status
Center Stack Module	B1A62 82	Rear Vision Camera Alive Sequence Counter Incorrect
Instrument Panel Cluster Control Module	U1008 00	Loss of Ethernet Link General Failure
Amplifier	B137B 11	Noise Reduction Microphone 1 Signal Circuit Short To Ground
Amplifier	B137C 11	Noise Reduction Microphone 2 Signal Circuit Short To Ground
Amplifier	B137D 11	Noise Reduction Microphone 3 Signal Circuit Short To Ground
Passenger Seat Adjuster Memory Module	U0418 00	Invalid Data Received from Brake System Control Module 1
Driver Seat Adjuster Memory Module	U0418 00	Invalid Data Received from Brake System Control Module 1
Driver Seat Adjuster Memory Module	U0209 00	Lost Communication with Seat Bolster Memory Control Module - Driver
Instrument Panel Cluster Control Module	U3003 16	Battery Voltage - Circuit Voltage Below Threshold
Telematic Control Module	U0146 00	Lost Communication with Central Gateway Module

Module	DTC #	DTC Long Name
Serial Data Gateway Module	U1962 00	Unable To Authenticate Serial Data Message
Amplifier	U1008 29	Loss of Ethernet Link Signal Invalid
Video Processing Module	U3002 56	Vehicle Identification Number - Invalid or Incompatible
Short Range Radar - Right Front	U0447 00	Invalid Data Received from Central Gateway Module
Electronic Brake Control Module	U0131 00	Lost Communication with Power Steering Control Module
Short Range Radar - Left Front	U0447 00	Invalid Data Received from Central Gateway Module
Short Range Radar - Left /Center Rear	U0447 00	Invalid Data Received from Central Gateway Module
Instrument Panel Cluster Control Module	U3000 09	Control Module Component Failure
Long Range Radar	U0447 00	Invalid Data Received from Central Gateway Module
Seat Belt Retractor Motor Module	U0422 00	Invalid Data Received from Body Control Module
Front View Camera	U0401 00	Invalid Data Received From Engine Control Module
Instrument Panel Cluster Control Module	U0131 00	Lost Communication with Power Steering Control Module
Amplifier	B137D 13	Noise Reduction Microphone 3 Signal Circuit Open
Center Stack Module	U3000 4B	Control Module Over Temperature
Remote Control Access Sensor	U1136 00	Lost Communication with Virtual Key Sensor - Two
Remote Control Access Sensor	U1138 00	Lost Communication with Virtual Key Sensor - Four
Power Steering Control Module	U3000 49	Control Module – Internal Electronic Failure

Parts Information

No parts are required for this repair.

Version	2
Modified	Released January 22, 2020 July 14, 2020 – Added the CT4 Model, Complete Update of DTC Table and Added Module column.