DIAGNOSTIC TOOL 2020-10

TRIUMPH

Notice Information

Ref	16091
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Service Leader / Advisor, Accounts / Admin
Subject:	Service/Technical

TOL NOTICE (US&CA) – October 6, 2020
TOL Ref. # 16091-SVC

DIAGNOSTIC TOOL 2020-10

Triumph has released version 2020-10 of the diagnostic software. It is now available to download and update on your workshop PC. Please download (from the Triumph Diagnostic Software page under the Service/Technical menu) today and commence using with immediate effect.

- Please ensure all new bikes have the latest software downloaded at PDI.

- Please ensure the latest software is downloaded on all bikes being serviced.

- **PLEASE ENSURE ALL RELEVANT STAFF ARE INFORMED OF THIS UPDATE.** (remember to update those returning from holidays/absence)

The release notes are stored and available to download at any time from the dedicated TDT page within TOL. Below is a summary of the changes in this latest version.

1. NEW SOFTWARE FUNCTIONALITY

- None

2. ENGINE ECM CALIBRATIONS

- Updated Engine ECM calibrations released for Bonneville T120, Bonneville T120 Black and Bonneville T120 Ace, Diamond and Bud Ekins Special Editions

3. CHASSIS ECM CALIBRATIONS

- Updated Chassis ECM calibrations released for Tiger 900, Tiger 900 GT, Tiger 900 GT-LRH, Tiger 900 GT Pro, Tiger 900 Rally and Tiger 900 Rally Pro.

4. INSTRUMENT CALIBRATIONS

- None

5. KEYLESS ECM CALIBRATIONS

- None

6. CONNECTIVITY MODULE CALIBRATIONS

- None

7. SUSPENSION ECM CALIBRATIONS

- None

8. NEW ECU UNLOCK CODES

- None

9. CALIBRATION DESCRIPTION CORRECTIONS

- None

10. KNOWN ISSUES IN THIS RELEASE

- None

11. BUG FIXES

- None

If you have questions, please contact Triumph Customer Support at (888) 284-6288.