GPOP - Issue Review System

Part Number: 68161086A$, 82211273A$, 82211272A$

Part Description: Tonneau Cover

Issue Description: For RAM Pickup Trucks with MOPAR Tonneau Covers that exhibit broken or non-functioning latches, please contact:

Chuck Hood at cell (248) 613-7591

If no response in 15 minutes, proceed with repair.

~_____~

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.