Mack Chassis - V-MAC III Only - Disable Eaton VORAD (EVT - 300) Collision Warning System/SmartCruise

👍 👎

> **Internal Content**

On a Mack Chassis (V-MAC III only) The procedure to disable the Eaton VORAD (EVT - 300) Collision Warning System/SmartCruise is found in the Eaton VORAD (EVT - 300) Collision Warning System/SmartCruise Troubleshooting Manual 8-335 posted in eMedia and MACK EIS. Refer to and follow the instructions - Eaton VORAD SmartCruise Disable Procedure found on page 59.

Note: Also you will have to disable in V-MAC III "Service Diagnostics" Adaptive Cruise Control Status Tab and program back to "Standard" Cruise Control in "Customer Data Programming Software" Customer Data/Vehicle ECU Tab & Program Cruise Control Tab.

Tags   k82422617   mack

Related links and attachments

No links or attachments available

Live UI

Feedback

Give feedback

to help improve the content of this article

to help improve the content of this article

Live UI