Preliminary Information

PIC6533 Diagnostic Tip – SPS Programming Saturn Vehicles

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Pontiac	Solstice	2006 - 2010	All	All	All	All
Saturn	Astra	2008 - 2009	All	All	All	All
Saturn	Aura	2007 - 2010	All	All	All	All
Saturn	Outlook	2007 - 2010	All	All	All	All
Saturn	Relay	2005 - 2007	All	All	All	All
Saturn	Sky	2007 - 2010	All	All	All	All
Saturn	Vue	2002 - 2010	All	All	All	All

Involved Region or Country	North America
Condition	Some technicians may have questions when programming modules equipped in the vehicles listed above.
Cause	Differences in programming content between the original Service Programming System and Techline Connect could result in errors when programming modules in these vehicles.

Correction:

If you experience the concern listed above, or encounter difficulties programming modules in these vehicles, call the Techline Customer Support Center (TCSC) at 800-828-6860.

Version History

Version	1
Modified	11/30/2023 - Created on.

GENERAL MOTORS