Preliminary Information

## PIT6142 No Cluster Graphics In Progressive Theme At Times

Models

Brand:	Model:	Model Years:	VIN: from	to	Engine:	Transmissions:
Chevrolet	Silverado 1500	2024	All	All	All	All
Chevrolet	Silverado 2500HD/3500HD	2024	All	All	All	All
GMC	Sierra 1500	2024	All	All	All	All
GMC	Sierra 2500HD/3500HD	2024	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	UDV
Condition	A customer may comment that there are no graphics displayed in the Cluster (IPC) at times after starting vehicle while viewing the Progressive Theme. Customer may indicate they can shut the vehicle off and restart or change to a different theme and graphics will return.
Cause	The cause of the condition may be software anomalies that Engineering is aware of.

Example Picture of Cluster with no graphics:

Currently GM Engineering is working on a repair. When a repair becomes available this PI will be updated.

Version History

Version	1
Modified	03/22/2024 - Created on.