CSC-10028181-6210

June 2008

«Name»
«Address»
«City», «State» «Zip»
«Country»

Technical Service Bulletin Notification

Unit Serial Number: «Serial»

Dear Jayco Dealer/Owner:

Jayco Inc. has become aware that on certain Jayco 2006 - 2007 Seneca 33SS motorhomes manufactured on a Kodiak chassis, the exhaust heat under heavy loads may cause the passenger side storage compartment to deform.

Our records indicate that your Seneca 33SS motorhome may be affected. Please contact your closest Jayco dealer to schedule an appointment. Present this letter as authorization to have the procedure completed at no cost to you. **The coverage period for this Technical Service Bulletin is for one (1) year from the original release of this notification**. If you have sold or traded your vehicle, or for any reason cannot have this service performed, please contact our customer service department @ 1-800-283-8267.

We apologize for this inconvenience. However, we are confident that this improvement will offer continued satisfaction with your Jayco Recreational Vehicle.

Sincerely,

Jayco, Inc.
Technical Research Department