



CSC-10043350-3578

December 27, 2011

CUSTOMER  
STREET  
CITY, STATE ZIP

**PRODUCT IMPROVEMENT CAMPAIGN: C1005010 Fuel Filter  
VEHICLES INVOLVED – Certain 2012 Model Year FEC52, FEC72, FEC92 and FGB72 Trucks**

**Vehicle Identification Number – VIN**

Dear Mitsubishi Fuso Truck Owner:

This notice is being sent to advise you about an important Product Improvement Campaign involving the Mitsubishi Fuso Truck identified above.

**REASON FOR THIS CAMPAIGN:** On affected vehicles, improper waterproofing at the fuel filter assembly water sensor may allow water to enter and short circuit the sensor, causing the "WATER SEPR" warning lamp to illuminate.

**WHAT WE WILL DO:** The fuel filter assembly will be inspected and if an affected assembly is found to be installed in your truck, it will be replaced. The procedure will be completed at no cost to you when performed by an Authorized Dealer or Parts and Service Center. The scheduled time for repair is approximately 0.5 to 0.6 hour.

**WHAT YOU SHOULD DO:** For your continued satisfaction, please contact any Authorized Mitsubishi Fuso Dealer or Parts and Service Center to schedule an appointment for this procedure. Refer to this Product Improvement Campaign Notification letter when speaking with Dealer Service Department personnel.

We at MFTA regret any inconvenience this situation may cause you. However, your continued satisfaction with our product is most important to us.

If an Authorized Dealer or Parts and Service Center is unable to perform this procedure without charge, or within a reasonable time frame, please contact MFTA Customer Service toll-free at 877-711-0707 for further assistance.

**Please note that this campaign will expire on December 27, 2012.**

Sincerely,

A handwritten signature in black ink that reads "William P. Mohr".

William P. Mohr  
Director, Service Operations