



Toyota Motor Sales, U.S.A., Inc.  
 19001 South Western Avenue  
 P.O. Box 2991  
 Torrance, CA 90509-2991

**PRODUCT UPDATE**  
**Owner's Manual Update**

[VIN]

Dear Toyota Owner:

At Toyota, we are dedicated to providing vehicles of outstanding quality and value. As part of our continual efforts to meet your product expectations, Toyota would like to advise you of a Product Update for your vehicle.

**What is the update?**

Due to an administrative error, the tire pressure to optimize ride comfort, tire wear and vehicle performance *when towing* was not correctly reflected in the Owner's Manual.

Model	Model Year	Current increase in psi when towing	Revised increase in psi when towing
Highlander (non-Hybrid)	2008 to	5 psi	6 psi
Highlander HV	certain 2012	N/A	3 psi

**What should you do?**

Please use the included installation instruction to apply the Owner's Manual Update Label(s) to the appropriate page(s).

If you would like to update your vehicle ownership or contact information, please go to [www.toyota.com/ownersupdate](http://www.toyota.com/ownersupdate). You will need your full 17-digit Vehicle Identification Number (VIN) to input the new information.

If you are a vehicle lessor, please assist us by forwarding this notice to the lessee.

We have sent this notice in the interest of your continued satisfaction with our products, and we sincerely regret any inconvenience this condition may have caused you.

Thank you for driving a Toyota.

Sincerely,

TOYOTA MOTOR SALES, U.S.A., INC.

Spanish translation on back side  
 Traducción en español en el lado inverso



Toyota Motor Sales, U.S.A., Inc.  
19001 South Western Avenue  
P.O. Box 2991  
Torrance, CA 90509-2991

**ACTUALIZACIÓN DE PRODUCTO**  
**Instrucciones de Instalación**

[VIN]

Estimado propietario de Toyota:

En Toyota, nos dedicamos a ofrecer vehículos de alta calidad y de valor superior. Como parte de nuestros esfuerzos continuos para satisfacer sus expectativas del producto, Toyota desea informarle sobre una actualización del producto para su vehículo.

**¿Cuál es la actualización?**

Debido a un error administrativo, la presión de los neumáticos para optimizar la comodidad de paseo, desgaste de los neumáticos y rendimiento del vehículo **durante el remolque** no fueron correctamente reflejados en el Manual del Propietario.

Modelo	Año Modelo	Incremento actual del psi durante el remolque	Incremento revisado del psi durante el remolque
Highlander (no híbrido)	2008 al ciertos de 2012	5 psi	6 psi
Highlander HV		N/A	3 psi

**¿Qué debería hacer?**

Por favor, utilice las instrucciones de instalación adjuntas para aplicar la(s) etiqueta(s) de Actualización del Manual de Propietario a la(s) página(s) correspondiente(s).

Si desea actualizar la información de contacto o de propiedad de su vehículo, puede hacerlo registrándose en [www.toyota.com/ownersupdate](http://www.toyota.com/ownersupdate). Necesitará su número de identificación del vehículo (VIN) completo de 17 dígitos para ingresar la nueva información.

Si usted arrienda el vehículo, ayúdenos entregando este aviso al arrendatario.

Le enviamos este aviso para que continúe satisfecho con nuestros productos y lamentamos sinceramente todo inconveniente que esta situación le haya causado.

Gracias por conducir un Toyota.

Atentamente,

TOYOTA MOTOR SALES, U.S.A., INC.  
COL

English version on front side  
Versión en inglés en el frente