



AUTOMOBILE DIVISION

American Honda Motor Co., Inc.
1919 Torrance Blvd., - P.O. Box 2215
Torrance, CA 90509-9870

CSC-10054242-8515

June 2014

RE: 2014 Accord Plug-In

Dear Honda Accord Plug-In Owner:

What is the reason for this notice?

Our records indicate that a PRODUCT UPDATE has not been completed on this vehicle; refer to the address card for the affected VIN. In some vehicles, the power control unit (PCU) coolant temperature sensor may fail. If it does, the gasoline engine will start unnecessarily while driving in battery electric mode, but the malfunction indicator lamp (MIL) will not come on.

What should you do?

Please contact any authorized Honda dealer to have your vehicle updated. This work will be done *free of charge*.

If you have questions

If you have any questions about this notice, or you need assistance locating a dealer, contact American Honda's customer service at 800-999-1009 and select option 4. You may also find this information at www.Hondacars.com.

We apologize for any inconvenience this product update may cause you.

Sincerely,

**American Honda Motor Co., Inc.
Honda Automobile Division**

NOTICE: If this is a leased vehicle, please forward this notice to the lessee.

FOR DEALER USE ONLY: REFERENCE SVC BULLETIN #13-039

S94



AUTOMOBILE DIVISION
American Honda Motor Co., Inc.
1919 Torrance Blvd., - P.O. Box 2215
Torrance, CA 90509-9870

Junio 2014

RE: Accord Plug-In 2014

Estimado propietario de un vehículo Honda Accord Plug-In:

¿Cuál es el motivo de esta notificación?

Nuestros registros indican que no se ha completado una ACTUALIZACIÓN DE PRODUCTO en este vehículo; consulte la tarjeta de dirección para ver el VIN afectado. En algunos vehículos, el sensor de temperatura del refrigerante de la unidad de control de potencia (PCU) puede fallar. Si falla, el motor a gasolina arrancará innecesariamente mientras se conduce en modalidad de batería eléctrica pero la luz indicadora de fallas (MIL) no se encenderá.

¿Qué debe hacer?

Por favor comuníquese con cualquier concesionario Honda autorizado para actualizar su vehículo. Este trabajo se realizará *sin costo alguno*.

Si tiene preguntas

Si tiene preguntas acerca de este aviso o necesita asistencia para ubicar un concesionario, comuníquese con el grupo de servicio al cliente de American Honda al 800-999-1009 y seleccione la opción 4. Usted también puede encontrar esta información en www.Hondacars.com.

Le pedimos disculpas por cualquier inconveniente que pueda haberle causado esta actualización de producto.

Atentamente,

American Honda Motor Co., Inc.
División Automotriz de Honda

AVISO: Si este es un vehículo arrendado, por favor envíe esta notificación al arrendatario.

PARA USO DEL CONCESIONARIO SOLAMENTE: REFERENCIA BOLETÍN DE SERVICIO #13-039
S94

**IMPORTANT: PRODUCT ADVISORY ENCLOSED
PLEASE OPEN IMMEDIATELY**

PLEASE DELIVER TO REGISTERED OWNER S94

VEHICLE
IDENTIFICATION ►
NUMBER

PRINTED PERF ▼ PLEASE DETACH, SIGN BELOW AND PLACE IN RETURN ENVELOPE ▼

INFORMATION CHANGE CARD

PLEASE PROVIDE NAME AND ADDRESS CORRECTIONS ON THE REVERSE SIDE

◀ VEHICLE IDENTIFICATION NUMBER S94

PLEASE SIGN AND RETURN THIS CARD
ONLY IF YOU HAVE MADE CHANGES

I no longer own the vehicle. It was:

- Sold (*print name and address of new owner on reverse, if known*)
- Exported
- Destroyed
- Stolen
- Lease expired, vehicle returned.
- Other: _____

Nota:

Si usted necesita esta información en español por favor comuníquese con Servicio al Cliente al 800-999-1009 y seleccione la opción 4.

Signature: **X** _____ Date: _____

SIGNATURE OF REGISTERED OWNER OR LESSEE REQUIRED

