



Mitsubishi Motors North America, Inc.

6400 Katella Avenue  
Cypress, CA 90630  
Telephone: 714-372-6000  
www.mitsubishicars.com

## CSC-10056653-3885

### AFFECTED VEHICLES

MODEL: 2008 – 2011 Lancer, 2009 – 2011 Lancer Sportback, 2008 – 2011 Outlander, and 2011 Outlander Sport

This notice applies to your vehicle, \_\_\_\_\_.

Date: August, 2014

Dear Mitsubishi Owner,

Mitsubishi Motors North America Inc. has determined that the front exhaust pipe seal ring on your vehicle may corrode from prolonged exposure to anti-freezing agents used in cold weather states to clear ice and snow from roadways.

To ensure your continued satisfaction with your vehicle, Mitsubishi is extending the warranty for the front exhaust pipe seal ring on your vehicle from the current 5 years / 60,000 miles to **10 years / 120,000 miles**, whichever comes first.

If you already had the front exhaust pipe seal ring replaced on your vehicle for this condition and paid for the repair, you may send your original repair order or invoice **and** original receipt/proof of payment to the following address for reimbursement consideration:

Mitsubishi Customer Relations Department, P.O. Box 6400, Cypress, CA 90630-0064

Please keep a copy of this notification with your vehicle's warranty book for future reference. If you have any questions, please contact us:

Mitsubishi Customer Relations Department • P.O. Box 6400 Cypress, CA 90630-0064  
Phone 1-888-648-7820 Hours: Monday – Friday 7 a.m. – 4 p.m. Pacific Time

Sincerely,

Mitsubishi Motors North America, Inc.

TSB-14-15-001