



903 South Main Street • P.O. Box 460 • Middlebury, IN 46540 • (574) 825-5861 • Fax (574) 825-7354

CSC-10057518-2430

February 2015

Technical Service Bulletin Notification TSB #15-002

Dear Valued Jayco RV Dealer:

Jayco has determined certain Model Year 2015 Seismic 4212 Fifth Wheels (9G) require removal of the microwave to reposition the vent fan to provide proper venting.

Our records indicate that the following Seismic Fifth Wheel/s are currently stock at your dealership and are included in this Bulletin:

The coverage period for this Technical Service Bulletin is for one (1) year from the release of this notification. (February 2015- February 2016). If you have sold this affected vehicle, please contact the current owner regarding this Service Bulletin and process the Warranty Registration for this customer. All pertinent information regarding this Bulletin is on file under the Service and Parts Tab of Jayco Partners. If you have questions regarding this Service Bulletin, please contact Jayco Customer Service at 800-283-8267.

We apologize for any inconvenience this may cause. However, we are confident that this improvement will offer continued satisfaction with your customer's Jayco Fifth Wheel.

Sincerely,

Jayco