

TO: Hyundai Dealership General Managers, Sales Managers,
Service Managers, Parts Managers, and Warranty
Administrators
FROM: Hyundai Motor America
DATE: October 25, 2013
SUBJECT: Glove Box Material Location Change

Effective 10/22/2013, 14 MY YF, and 13 MY UD glove box materials that were previously placed in the glove box, will now be assembled in a plastic bag and placed in the trunk. Please ensure to get this message out to all appropriate personnel at your dealerships.

Hyundai appreciates your cooperation and support. Questions may be directed to your District Parts and Service Manager or Warranty HELPREP line at 1-877-446-2922.

HYUNDAI MOTOR AMERICA