

TO: Hyundai Dealership General Managers, Sales Managers,
Service Managers, Parts Managers, and Warranty
Administrators
FROM: Hyundai Motor America
DATE: February 5, 2013
SUBJECT: Recall 108 - Veloster Panoramic Sunroof Inspection Kit
- Tube Measurement

Hyundai Motor America is requesting all Dealers to measure ALL the PVC pipes (00305 FSPVC) provided in the Inspection Kit (00305 FSKIT). Some of the PVC pipes provided maybe longer than the required length specification of $19.5'' \pm 0.5''$. Please do the following:

- Measure the length of the two (2) PVC tubes received in the 00305-FSKIT to ensure they meet the required length specification ($19.5'' \pm 0.5''$).
- If the PVC tube DOES NOT meet the required length specification, please cut any length beyond $19.5'' \pm 0.5''$ BEFORE conducting any additional vehicle inspections.

Using PVC tube longer than $19.5'' \pm 0.5''$ may result in unnecessary glass replacement.

Hyundai appreciates your cooperation and support. Questions may be directed to your District Parts and Service Manager or Warranty HELPREP line at 1-877-446-2922.

HYUNDAI MOTOR AMERICA