

//ALL 05/29/2013 to 06/28/2013
TO: Hyundai Dealership General Managers, Sales Managers,
Service Managers, Parts Managers, and Warranty
Administrators
FROM: Hyundai Motor America
DATE: May 28, 2013
SUBJECT: **Revised: Service Campaign TL6 - Equus, Genesis Sedan
Brake Fluid Replacement - TSB# 13-01-006-2 - Removed Sublet
Amount**

Effective May 28, 2013, Hyundai Motor America is removing the \$23.40 sublet amount and placing the DOT 4 brake fluid part number as the replacement part for Service Campaign TL6 - Equus and Genesis Sedan brake fluid replacement.

In order to identify only those vehicles affected by Service Campaign TL6, it will be necessary to access Hyundai Motor America's "Warranty Vehicle Information" screen via WEBDCS before starting the repair. The "Warranty Vehicle Information" screen will identify affected vehicles with an open Service Campaign TL6.

A listing of DEALER STOCK AND RETAILED VEHICLES is also located on WEBDCS, SERVICE tab, select INFORMATION, and select: UNCOMPLETED CAMPAIGN VIN LIST - DEALER STOCK OR RETAILED.

Supersede TSB #13-01-006-2 for Service Campaign TL6 is available on HMAservice.com as of May 28, 2013. It contains instructions on performing the service and submitting the service campaign claim.

It is IMPORTANT TO SUBMIT A CAMPAIGN CLAIM FOR EACH VEHICLE SERVICED so your dealership can be compensated for your work and Hyundai can maintain accurate records of campaign completions.

LEGAL LIABILITY NOTICE: You are required to keep confidential any and all information and documents provided to you by Hyundai Motor America in the conduct of carrying out work for this Service Campaign. Hyundai Motor America dealers may use owner information provided for the campaign only for the purpose of conducting and performing this service campaign, and for no other purpose.

Hyundai appreciates your cooperation and support. Questions may be directed to your District Parts and Service Manager or Warranty HELPREP line at 1-877-446-2922.

HYUNDAI MOTOR AMERICA