



Tech Tips

TT 20-13-03

Date: July 12, 2013

2009-2013 Tiguan – In-Tank Fuel Pump Pressure Specified Value

July 19, 2013: Update to Information.

Be aware that the specified value for pressure from the in-tank (low side) fuel pump is 3.7 bar or higher.